2	Administration Approval & Date	JC/RRNZ/AS/2952/2013-14 Dtd.05-03-2014 by JC (RRNZ)
3	Technical Sanction Estimate No.& Date	EE/RRND/TS/13/2014-15 Dtd: 16-06-2014 by EE(RRND)
4	Estimate Amount	Rs.8.00 Lakhs
5	Job Code No.	016-14-000030
6	P-Code	P-2178
7	Agreement No & date	EE/RRND/AG.No./33/2014-15 Dtd.20-06-2014
8	Work order Number & Date	EE/RRND/Wo.No./33/2014-15 Dtd.20-06-2014
9	Contract Amount as per Agreement	Rs. 800,000/-
10	Bill Amount	Rs.8,87690 /- including KRIDL Charges
11	B.R. No. & Date	284/2014-15 Dtd: 31-7-2014
12	Agency	KRIDL, Bangaluru
13	M.B. Number & Page No. of Measurement recordes	1812/14-15 Pages 181109 to 181119 (Xerox Copy of MB)
14	Date of Inspection	1 - 1 - 2016
15	Enclosures	1) 2 Number of photos taken during inspection
16	Inspection Report	The above site has been Inspected by me along with the Concerned person. It is observed that the bore has been drilled and is Connected to the Cystern for providing Drinking water to the residents of the area. The bore is functioning. This has a reference to the Xerox Copy of MB No 1812

EE RRND, RR Nagara Zone

(R.Sathyanarayana)
Inspection Report officer,